MHT No. B-4534

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Name and SHA No. Pennington Avenue Bridge (CC5217)
Location: Street/Road Name and Number: Pennington Ave. over Curtis Creek
City/Town: <u>Baltimore</u> vicinity
County: <u>Baltimore</u>
Ownership:StateCounty _x_MunicipalOther
This bridge projects over:RoadRailway _x_WaterLand
Is the bridge located within a designated district:yes _x_noNR listed districtNR determined eligible districtlocally designatedother Name of District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
_Stone Arch
Metal Truss Bridge
<u>x</u> Movable Bridge  _Swing _Bascule Single Leaf <u>x</u> Bascule Multiple Leaf _Vertical Lift _Retractile _Pontoon
Metal GirderRolled GirderRolled Girder Concrete EncasedPlate GirderPlate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
ConcreteConcrete ArchConcrete SlabConcrete BeamRigid FrameOther Type Name

B-4534

# Description:

### **Describe Setting:**

The Pennington Avenue Bridge is located in an industrial section of the outer harbor of Baltimore. It crosses Curtis Creek in an east-west direction. Views of the bridge are obstructed by I-695, the Baltimore Beltway, and Maryland Route 710. All roads in the immediate area are heavily traveled.

# **Describe Superstructure and Substructure:**

The current Pennington Avenue Bridge is a steel, multibeam double leaf trunnion bascule. A trunnion bascule, or a simple bascule, as it is also sometimes called, is one in which the movable span swings upward around a central pivot at the center of rotation. Fenders built in the water at the corner of each movable span protect the spans from possible impact from ships passing through the channel. The overall length of the Pennington Avenue Bridge is 1,912 feet. There are 16 concrete approach spans in the westbound lanes and 15 in the eastbound lanes, as well as the main bascule span. The width of the roadway is approximately 66 feet. The length of the longest span is 317 feet. The roadway is surfaced with concrete and open steel grid over the draw span. There is no sidewalk. The main trunnion bearing housing is approximately 6 feet in height. The bridge was rebuilt in 1976.

# Discuss major alterations:

Photographs of an earlier bridge, constructed in 1930-31, show it having four identical houses, one at each corner of the draw span. Early bridge engineers encouraged the construction of four houses, if there was room on the bridge, in the interest of symmetry. This symmetrical structure was replaced by the current bridge in 1976.

#### History:

When Built: 1976

Why Built: To replace a former bridge. Who Built: State Highway Administration Who Designed: Zollman Associates

Why Altered: Unknown

Was this bridge built as part of an organized bridge building campaign: No.

### Surveyor Analysis:

This bridge may have NR significance for association with:

\_A Events \_B Person

\_\_C Engineering/Architectural Character

Was the bridge constructed in response to significant events in Maryland or local history?

The current replacement bridge does not appear to have been constructed in response to any significant State or local events.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

While its precise influence on the growth and development of Baltimore at the time of its construction is not known with certainty, it is presumed that an improved crossing at this point, with a capability to handle increased traffic loads, volumes, and speeds, would have had a positive impact on the city by facilitating the transport of goods and services.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic and visual character of the possible district?

The Pennington Avenue Bridge is not in an area that currently appears to be eligible for listing in the National Register of Historic Places. The bridge has lost its integrity of setting with the construction of the Baltimore Beltway and MD Route 710. It would neither add to nor detract from any historic district that might be designated.

# Is the bridge a significant example of its type?

The Pennington Avenue Bridge is one of only 20 bascule bridges remaining in Maryland. Bascule bridges currently are more common than other forms of movable bridges in Maryland. They were the earliest type of movable bridges, and although swing bridges, for a time gained precedence, bascule bridges garnered renewed interest with the development by the State Roads Commission of reinforced concrete bridges (Spero 1994). However, because it is less than 50 years old, the Pennington Avenue Bridge is not eligible for listing in the National Register.

Does the bridge retain integrity of the important elements described in the Context Addendum?

The Pennington Avenue Bridge retains its bascule span, its fender system, its dolphins, and its bridge tender's house.

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer and why?

The bridge is too recent to determine whether it is a significant example of the work of Zollman Associates.

Should this bridge be given further study before significance analysis is made and why?

No further study is required to determine that the bridge lacks historical significance.

Provide black and white prints and negatives and color slides of bridge, details, and setting labeled according to NR Bulletin 16A and Maryland Supplement to Bulletin 16A.

Provide a photocopy USGS map illustrating the location of the bridge.

Surveyor:

Name:

Alice Crampton/Julie Abell

Date:

12/9/94

Organization:

Parsons Engineering Science, Inc.


Telephone:

(703) 591-7575


Address:


10521 Rosehaven Street

Fairfax, Virginia 22030-2899



B-4534 Pennington Avenue Bridge (BC5217) Pennington Avenue over Curtis Creek Baltimore City CUrtis Bay Quad







Pennington Avenue Bridge (BC5217) Baltimore County, Marylan & John Rutherford Maryland State Highway Administration South elevation (background)



B-4534 Pennington Avenue Bridge (BC5217) Baltimore County, Maryland John Rutherford Maryland State Highway Administration North elevation 2 of 5



Baltimore County, Maryland John Rutherford Maryland State Highway Administration North elevation, drawspan detail 3 of 5



B-4534 Pennington Avenue Bridge (BC5217) Baltimore County, Maryland Julie Abell

Approach looking west

4 of 5

Maryland State Highway Administration



Pennington Avenue Bridge (BC5217) Baltimore County, Manyland Julie Abell 12/94 Manyland State Highway Administration Approach looking east 5 of 5